DEPAR	TMENT OF HEALTH	AND HUMAN SERVICES			RINTED	: 04/03/2014	
CENTE	RS FOR MEDICARE	& MEDICAID SERVICES	45	5//8//9		APPROVED 0938-0391	
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIE IDENTIFICATION NUM		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	COOLAND TIPLE CONTRACTOR CONTRACTOR		(X3) DA1	X3) DATE SURVEY COMPLETED	
		445242	B. WING_	· · · · · · · · · · · · · · · · · · ·	04	/01/2014	
NAME OF	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE	<u> </u>	V 112V 14	
GREYS1	ONE HEALTH CARE			181 DUNLAP ROAD BLOUNTVILLE, TN 37617	•		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPI DEFICIENCY)	SHOULD BE COMPLETION		
K 020 SS≃D			K 02	K020 HVAC Inc. Building Solutions was contacted April 7, 2014, By our Maintenance director		5/17/2014	
	between floors are e having a fire resistar	enclosed with construction nce rating of at least one y be used in accordance with		Install 2 fire dampers. A quotation has be received 4/21/14 and approved.			
	This STANDARD is			The facility maintenance director has inspeal remaining day rooms for ventilation chensure they have 1 hour fire rating 4/21/	utes to		
-	Based on observati determined that the	not met as evidenced by: on and interview, it was facility falled to maintain th at least a one hour fire		The center continues to maintain weekly, monthly fire safety building inspections to for proper fire resistance ratings and opera. The facility plant operations manager cont to report his findings to the safety commit monthly. All reports are discussed for actions.	ition. Inues tee		
	director on April 1, 2	erview with the maintenance 014 at 2:00 p.m. revealed aft that serves the first floor	•	discussed at our April Safety Committee n 4/22/14.			
	conference room, se third floor day room in ventilation shaft in ea the ventilation shaft in	econd floor day room, and has an opening from the ach of the three rooms and is not protected with any fire the three story ventilation		All fire safety inspection reports conducte the plant operations director or fire safety inspector and reported to the safety commare forwarded to the facility Quality Assu Committee for trending, and recommendate beginning with the April 2014 meeting.	nittee rance		
	director and acknowledged during the exit confe	fled by the maintenance ledged by the administrator rence on April 1, 2014. ETY CODE STANDARD	K 045	K045			
	discharge, is arrange lighting fixture (bulb)	s of egress, including exited so that failure of any single will not leave the area in so not refer to emergency with section 7.8.)	•	The maintenance director will install lightly the exit path walkway along the central statexit egress by May 1, 2014.	ng on ir well		
YANTARORA	DIDECTOR'S ON SECULIA	Diction in organia	,			<u>, </u>	
	Mish.	RYSUPPLIER REPRESENTATIVE'S SIGN	ATURE /	b). THE	1/	X6) DATE	

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is regulate to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: 9XSO21

Facility ID: TN8204

If continuation sheet Page 1 of 4

PRINTED: 04/03/2014

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

FORM APPROVED OMB NO. 0938-0391 STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION (X3) DATE SURVEY COMPLETED IDENTIFICATION NUMBER: A. BUILDING 01 - MAIN BUILDING 01 445242 B. WING 04/01/2014 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 181 DUNLAP ROAD **GREYSTONE HEALTH CARE CENTER** BLOUNTVILLE, TN 37617 SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PROVIDER'S PLAN OF CORRECTION (EACH DEFICIENCY MUST BE PRECEDED BY FULL PRÉFIX (X5) COMPLETION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DATE DEFICIENCY) K 045 Continued From page 1 K 045 The facility maintenance director has inspected all exit paths connected to the center exit doors to ensure all areas have lighting adequate to use for evacuating the center as of April 21, 2014. This STANDARD is not met as evidenced by: Based on observation and interview, it was determined that the facility failed to have ensure All exterior lighting is being checked by our plant exit paths have lighting so that the area will not be operations manager or designee during weekly in total darkness. safety check rounds. Results of the safety rounds reported to the center safety committee The findings include: beginning April 22, 2014. Observation and interview with the maintenance director on April 1, 2014 at 10:15 a.m. revealed that the exit discharge from the central stairwell is not provided with lighting that is also on All safety reports and findings presented at the emergency power. center safety committee meeting are trended and reported for recommendations to the This finding was verified by the maintenance Center Quality Assurance Committee monthly director and acknowledged by the administrator beginning April 2014. during the exit conference on April 1, 2014. K 077 NFPA 101 LIFE SAFETY CODE STANDARD K 077 K077 SS=D Piped in medical gas systems comply with NFPA The center currently has on hand a combination 99, Chapter 4. of H-tanks and E-tanks to provide 24 hour emergency supply of Oxygen effective April 25, 2014. This STANDARD is not met as evidenced by: The center has received a proposal to install a Based on record review, it was determined that new Oxygen manifold and to complete wiring to the facility failed to maintain piped in medical our alarm panel for a master alarm. The proposal from Allied Piping Company has been gasses in accordance with NFPA 99. received and approved April 22, 2014. The findings include: All residents that require Oxygen have available a Record review on April 1, 2014 at 1:10 p.m. measured amount of Oxygen and have available revealed that the annual medical gas report a backup 24 hour revealed the following deficiencies: The emergency oxygen reserve is not

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/03/2014 FORM APPROVED OMB NO. 0938-0391

SERVICES OF PERSONNELLING AND SERVICES			OMB NO. 0938-03					
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01		(X3) DATE SURVEY COMPLETED		
	445242		8. WING		04/01/2014			
NAME OF	PROVIDER OR SUPPLIER			S	STREET ADDRESS, CITY, STATE, ZIP CODE		04/01/2014	
GREYST	ONE HEALTH CARE	CENTER			81 DUNLAP ROAD	-		
				-	BLOUNTVILLE, TN 37617			
(X4) IO PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE ACTION SH		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPR DEFICIENCY)	ORF COMPLET		
K 077	capable of supplyin 2. The emergency signal to the Master emergency reserve These findings were director and acknow	apable of supplying oxygen for at least 24 hours. The emergency oxygen does not send a ignal to the Master Alarm indicating the mergency reserve is in use. K 077 The inspection reports are presented occur at our Safety committee for active beginning April 2014 meeting. All Safety committee reports are trensforwarded to the center Quality Assumes findings were verified by the maintenance.		occur at our Safety committee for action	er they I and			
K 108 SS≕D	NFPA 101 LIFE SAFETY CODE STANDARD Hospitals, and nursing homes and hospices with life support equipment, have a Type I Essential Electrical System powered by a generator with a transfer switch and separate power supply. The EES is in accordance with NFPA 99, 3.4.2.2, 3.4.2.1.4.			06	K106 The facility currently has (2) operating generators and (2) transfer switches. The center contacted Nixon Power Services for an assessment of the center generators. On April 16, 2014 Nixon Power assessment was completed. Upon completion of their assessment they concluded that the center is currently operating with a Type I Essential Electrical System in written correspondence dated April 16, 2014			
	Based on observati facility falled to have System for life supp	1			All residents requiring life support equipme located in rooms with the Type I Essential Electrical System supporting electrical circu	its.	,	
	revealed that the em	11, 2014 at 11:10 a.m. Pergency generator is not e 1 Essential Electrical	- , ·	ţ	Routine generator inspections will continue completed weekly, and monthly by in house maintenance. An annual 4 hour load bank completed annually by vendor. Results of inspections will be reviewed and forward to monthly safety committee.	se test is f the		
	This finding was ver director and acknow during the exit confe	ified by the maintenance ledged by the administrator prence on April 1, 2014. ETY CODE STANDARD	K 1	47	Results of all generator inspections reported monthly to our center safety committee with the reported to our Quality Assurance Comfor recommended actions beginning with the April 2014 meeting.	ili then mittee		

DEPAR CENTE	TMENT OF HEALTH	AND HUMAN SERVICES				FORM): 04/03/2014 MAPPROVED
CENTERS FOR MEDICARE & MEDICAID SERVICES STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01			OMB NO. 0938-0391 (X3) DATE SURVEY COMPLETED		
w		445242	8. WING	3		04	/01/2014
-	PROVIDER OR SUPPLIER ONE HEALTH CARE (1	TREET ADDRESS, CITY, STATE, ZIP CODE 81 DUNLAP ROAD BLOUNTVILLE, TN 37617		101/2014
PREFIX	(EACH DEFICIENCY	MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	PREF TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPI DEFICIENCY)	RE	(X5) COMPLETION DATE
K 147 SS=E	Electrical wiring and equipment is in accordance with NFPA 70, National Electrical Code. 9.1.2 This STANDARD is not met as evidenced by: Based on observation and testing, it was determined that the facility failed to install ground fault circuit interrupter (GFCI) in wet areas. The findings include: Observation and testing on April 1, 2014 at 2:05 p.m. revealed the electrical outlets at sinks located in the resident rooms were not equipped with ground fault circuit interrupter (GFCI) outlets. The following rooms were not provided with ground fault circuit interrupters outlets (GFCI): Resident room 308. Resident room 329. Resident room 234. Resident room 232. These findings were verified by the maintenance director and acknowledged by the administrator during the exit conference on April 1, 2014.		K 1	147	K147 Maintenance Director will install GFCI electrical outlets at sinks in rooms 308, 329, 232, 234, 232.		
					Maintenance Director and or designee will all electrical outlets in the building located sinks to ensure they all are GFCI type by 5, All electrical outlets near sinks that are GF protected will be checked 1 x per quarter quarters beginning in May 2014. Outlets twill be checked semi-annually beginning November 2014 Electrical outlet audits completed 1 x per for 2 quarters then semi-annually results submitted to the Quality Assurance Commonthly as scheduled for review and recommendations, beginning with the Mameeting.	I near /7/14. CI for 2 then quarter will be	
	-			İ			